

#3519  
December 17, 2019  
Page 1 of 1

SUBJECT: P/N 29546675 — 4th Generation A46 TCM Product Discontinuation

MODELS AFFECTED: Various

**Introduction:**

The 4th Generation A46 TCM will no longer be offered by Allison Transmission.

**Serviceability:**

To continue servicing vehicles, customers will need to go to a local GM Dealer to purchase the 4th Generation A46 TCM equivalent, GM's T14A TCM (P/N 24256864). Allison TCM Reflash™ V6.2 is needed to reflash the GM T14A TCM.

Old Part Number	Supplier	New Part Number	Supplier
29546675 – A46	Allison Transmission	24256864 – T14A	General Motors

In order to install the correct calibration in the new TCM, please contact your nearest Allison authorized distributor via the Sales and Service locator at [www.allisontransmission.com](http://www.allisontransmission.com). The new TCM will need to be taken to the location in order to be Reflashed with the correct calibration. Charges may apply for this additional required service.